

On Wed, Dec 24, 2014 at 8:44 AM, Lively, Kevin W

<Kevin.Lively@kindermorgan.com> wrote:

5/14/2014 J. Vedsted

On location. Initial well condition: dead. Archer Wire Line on location. Safety meeting and indoctrination with 4 wire line hands. Remove 3" ball valve from well head and install 2 7/8" TIW valve. Start in hole with overshot for W wire line plug.

Tag plug. POOH. Out of hole with no plug. RIH and tag plug or fill. 1250# pull on wire. POOH. Out of hole, no plug. Fill casing with KCL water and perforate at 50'. Out of hole and lay down gun. Go to Flank 10.

5.22.14 J Vedsted

On location. Water Truck on location. Rig crew and Basic Energy on location. Pump 4 bbls of water ahead. Mix 15.6 #/gal cement - 9 1/2 bbl volume. Displace with 2 bbls water. Depth of 1st plug - 4,036' to 2,222' (tubing out). Lay down 58 joints tubing. (Fluid level at 45' down on tubing) Key winch truck on location. Pump 3 bbls water ahead. Mix cement - 50 sacks (10.5 bbls) Depth 2 plug - 2116' to 29'. Plug down. Lay down remainder of tubing to trailer. Pump 75 sacks cement down "casing" - with blow on surface casing. Pressure increased to 700 psi. Shut in surface valve with 200 psi. Pump down surface casing - 25 sacks cement. Wash cement truck up to tank and hauled to disposal. Rig down work over unit, haul tubing string to Morton Station. Off location. No accidents or injuries.

Kevin Lively

Natural Gas Storage Group

[719-520-4287](tel:719-520-4287) -office

[970-380-6011](tel:970-380-6011) - cell

KINDER MORGAN