



REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

To: District Engineer ~~XXXXX~~ BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 150 inj. water BBLS Lost: 150 inj. water
3. Contained on location: Yes X No _____
4. Date and time of event: 03/02/88 4:30 PM
BLM
5. Date and time reported to ~~XXXXX~~: 03/04/88 8:45 AM Louise McMinn
6. Location of event: NE SE Sec 21, T2N, R102W
7. Specific nature and cause of event

Failure in weld.
8. Describe resultant damage:

N/A
9. Time required for control of event: 15 min.
10. Action taken to control and contain:
Water mixed w/snow melt - unable to recover. Injection line was shut in upon discovery. No water reached a navigable waterway.
11. Action taken to prevent recurrence:-
Replaced piece of pipe.
12. Cause of death:

N/A
13. Other agencies notified:
Colorado Department of Health, Air Quality Control, Denver, Co.
Colorado Oil and Gas Conservation Commission, Denver, Co - Written Report Only
14. Other pertinent information:

Signature T. L. Hurst Date 3/10/88
T. L. Hurst
Title Area Unit Supervisor