

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401175486

Date Received:

12/29/2016

Spill report taken by:

Kosola, Jason

Spill/Release Point ID:

446695

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>PIONEER NATURAL RESOURCES USA INC</u>	Operator No: <u>10084</u>	<b>Phone Numbers</b>
Address: <u>5205 N O'CONNOR BLVD STE 200</u>		Phone: <u>(719) 846-7898</u>
City: <u>IRVING</u>	State: <u>TX</u>	Zip: <u>75039</u>
Contact Person: <u>Cherylyn Morgan</u>		Mobile: <u>( )</u>
		Email: <u>cherylyn.morgan@pxd.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401079652

Initial Report Date: 07/18/2016 Date of Discovery: 07/15/2016 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWSE SEC 10 TWP 33S RNG 65W MERIDIAN 6

Latitude: 37.183700 Longitude: -104.662530

Municipality (if within municipal boundaries): \_\_\_\_\_ County: LAS ANIMAS

#### Reference Location:

Facility Type: WATER GATHERING SYSTEM/LINE ☒ Facility/Location ID No 427440

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Hot Sunny

Surface Owner: FEE Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

We had a spill that was found on 7/15/16 at around 10 AM on the Midway 23-10 (API 05-071-06546) well site. The leak was isolated upon discovery and it appears to be a break in the gathering line at the well head. It is estimated that 5bbls of produced water were spilled with no state waters involved. The spill did leave the location running off of the north side ending before it crossed the lease road

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
7/15/2016	COGCC	Jason Kosola	-	email
7/15/2016	LACOG	Bob Lucero	-	email
7/15/2016	Land owner	Ed Shanon	-	Two attempts by phone were made

**SPILL/RELEASE DETAIL REPORTS**

#1	Supplemental Report Date: 12/29/2016		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	5	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>90</u>		Width of Impact (feet): <u>1</u>	
Depth of Impact (feet BGS): <u>0</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
GPS and Visual inspection			
Soil/Geology Description:			
From the NRCS soil surevy map: Lorencito-Sarcillo-Trujillo Complex			
Depth to Groundwater (feet BGS) <u>100</u>		Number Water Wells within 1/2 mile radius: <u>4</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1060</u> None <input type="checkbox"/>	Surface Water <u>915</u> None <input type="checkbox"/>	
	Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>1285</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

During Repairs there was a steel 2" T that had a pin hole in it from corrosion

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 12/29/2016

Cause of Spill (Check all that apply) ☒ Human Error ☐ Equipment Failure ☐ Historical-Unknown  
☐ Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

There was no protective coating on the pipe to protect it from corrosion: Root cause was mechanical failure due to inadequate

Describe measures taken to prevent the problem(s) from reoccurring:

Proper repairs were made with proper installation. a protective coating was added to the pipe.

Volume of Soil Excavated (cubic yards): \_\_\_\_\_

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment  
☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

## OPERATOR COMMENTS:

Produced water quality data from the well associated with or representative of the spill is attached. Pioneer and its consulting geochemical specialists have found, after 20 years operating in the Raton Basin CBM field, that soil sampling no longer adds useful data on smaller, short-term spills as land uses and the environment are not sensitive to short-term exposure to CBM produced water. Effects to soil chemistry from short-term CBM produced water spills are temporary and shallow for several reasons: the water does not contain crude oil or liquid hydrocarbons; the TDS is significantly less than 10,000 mg/L; it is suitable for livestock watering, wildlife and in many cases surface discharge. Mixed with other water it is suitable for irrigation without impact. When requested by the agency or landowner Pioneer has and will collect soil samples. Pioneer Natural Resources request closure of this spill based on this statement and attached water quality data.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Cherylyn Morgan  
Title: Environmental Technician Date: 12/29/2016 Email: cherylyn.morgan@pxd.com

## COA Type

## Description

--	--

## Attachment Check List

### Att Doc Num

### Name

401175506

Total Attach: 1 Files

**General Comments**

<u><b>User Group</b></u>	<u><b>Comment</b></u>	<u><b>Comment Date</b></u>
		Stamp Upon Approval

Total: 0 comment(s)