FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



FIELD INSPECTION FORM

Loc ID	Inspector Nam	ne:	On-Site Ir	nspection	<u>Sta</u>	tus Summary:			
311674 Colby, Lou			2A	2A Doc Num:		THIS IS A FOLLOW UP INSPECTION			
Operator In	formation:				X	FOLLOW UP INSPECTION REQUIRED			
OGCC Operator Number: 10456						NO FOLLOW UP INSPECTION R	REQUIRED		
Name of Op	erator: CAERUS F	PICEANCE	LLC		<u>Fin</u>	Findings:			
Address: 1	Address: 1001 17TH STREET #1600 6 Number of Comments 1 Number of Corrective Actions								
City:	DENVER	State:	СО	Zip: 8020	<u></u>	Corrective Action Response Requeste			
Contact Information:									
Contact Name Phone			е	Email		Comment			
,				cogcc.inspection	ons@caerusoi	la			
Inspected Facilities:									
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status		
275038	WELL	PR	10/16/2005	GW	045-13458	N.PARACHUTE WF04D B04 596	RI		
275043	WELL	PR	12/07/2004	GW	045-13463	N,PARACHUTE WF03D B04 596	RI		

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

mopostor rec	arric. Colby, E						
Inspected Facilities							
				•			
Facility ID:	275038	Type:	WELL	API Number:	045-13458	Status: PR	Insp. Status: RI
Facility ID:	275043	Type: _	WELL	API Number:	045-13463	Status: PR	Insp. Status: RI

Reclamation - Storm Water - Pit					
Interim Reclamation:					
Date Interim Recl	amation Started: Date Interim Reclamation Completed:				
Land Use:					
Comment:					
1002 SITE PREPAR	ATION AND STABILIZATION				
1002a. FENCIN					
Comment					
Corrective Action		Date			
1002b. SOIL RE SEGRE					
Comment					
Corrective Action		Date			
1002c. PROTEC	CTION OF SOILS				
Comment					
Corrective Action		Date			
1002E. SURFAC	CE DISTRURBANCE MINIMIZATION				
Comment					
Corrective Action		Date			
1003a. Waste a	nd Debris removed? Pass				
Comment					
Corrective Action		Date			
Unused	or unneeded equipment onsite? Pass				
Comment					
Corrective Action		Date			
Pit, cel	lars, rat holes and other bores closed? Pass				
Comment					
Corrective Action		Date			
Guy line	anchors marked?				
Comment [
Corrective Action		Date			

Inspector Name: Colby, Lou 1003b. Area no longer in use? Pass Production areas stabilized? Pass 1003c. Compacted areas have been cross ripped? Pass 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Cuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Production areas have been stabilized? Pass Segregated soils have been replaced? RESTORATION AND REVEGETATION Cropland Top soil replaced Recontoured Perennial forage re-established Non-Cropland Top soil replaced Recontoured Pass 80% Revegetation In 1003e. INTERIM VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER 1003 f. Weeds Noxious weeds? Comment Location appears well maintained and Vegetation in Interim Reclamation areas well established. Corrective Action Date Overall Interim Reclamation In Process Final Reclamation/ Abandoned Location: Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Well plugged Pit mouse/rat holes, cellars backfilled Debris removed No disturbance /Location never built Contoured Culverts removed Access Roads Regraded Gravel removed Location and associated production facilities reclaimed Locations, facilities, roads, recontoured Compaction alleviation Dust and erosion control Cropland: perennial forage Non cropland: Revegetated 80% Weeds present Subsidence 1004.d. FINAL VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER Comment: Corrective Action: Well Release on Active Location Overall Final Reclamation Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Fail			East side
Compaction						Could be better
Gravel						Could be better
Ditches	Pass					
			_			

Comment: 1) East side of Access road ditch needs maintenance.

2)Plowing has moved material off road into edge of Reclamation area; creating disturbance & opportunity for small amount of Sediment migration; this will need to be monitored. Refer to Photos attached.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

NO SURFACE INDICATION OF PIT Pits:

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
401597561	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425336
680102827	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4425334

Date: 05/04/2018