

LEON RODAK
MURFIN DRILLING COMPANY INC
250 N WATER ST STE 300
WICHITA KS 67202

Dear Mr. Rodak,

MURFIN DRILLING COMPANY INC is receiving this letter because, based on COGCC records, the COGCC has reason to believe that in addition to the Well on the Warning Letter the Well provided below present one or more compliance issues. The Well provided below must be brought into compliance or be compliant by the date provided on the Warning Letter. Please do not hesitate to contact me with any questions regarding this compliance issue, or if this Well is incorrectly reported as non-compliant.

1. S.E. CAMPO UNIT 605 -API# 009-06500

Thank you,

Ryan Daigle

Engineering Technician



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

P 303.894.2100 x5168 | F 303.894.2105

1120 Lincoln Street, Suite 801, Denver, CO 80203

ryan.daigle@state.co.us | www.colorado.gov/cogcc