

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401712362

Date Received:

07/24/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

720-315-8934

Lkelly@Bonanzacrk.com

Brian Dodek

720-440-6100

BDodek@Bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403680

Inspection Date: 06/11/2018

FIR Submit Date: 06/13/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 436197

Location Name: Pronghorn Number: F-18 Pad County: _____

Qtrqtr: NENW Sec: 18 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.407330 Longitude: -104.256630

FACILITY - API Number: 05-123-00 Facility ID: 436197

Facility Name: Pronghorn Number: F-18 Pad

Qtrqtr: NENW Sec: 18 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.407330 Longitude: -104.256630

CORRECTIVE ACTIONS:

1 CA# 116770

Corrective Action: Operator shall implement Best Management Practices per Rule 603.f. to control and manage weeds to prevent weed waste and to prevent the spread of dispersing seeds onto adjacent lands.

Date: 07/11/2018

Response: CA COMPLETED

Date of Completion: 07/10/2018

In compliance with Rule 603.f the entire location was mowed and all of the weeds were removed. Please see the attached pictures for verification. Pad expansion activities are currently in progress.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 116771

Corrective Action: Operator shall comply with Rule 1003 standards for the northeastern interim areas that will not be needed for future operations. This is not the ideal time to reseed but the Operator shall, at a minimum, stabilize the northeastern interim area, as these areas are susceptible to further wind erosion.

Date: 07/11/2018

Response: CA COMPLETED

Date of Completion: 07/23/2018

Operator
Comment:

As discussed in a follow up conversation, the northeastern section of the interim reclaim noted in this CA will be redisturbed by drilling and completion activities. The topsoil was scraped off of the interim reclaim and stockpiled. Upon completion of the pad expansion, road base will be spread to stabilize the location. Interim reclamation will take place within 6 months of the first date of production. Please see the attached pictures of active construction in the area of concern.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Kelly

Signed:

Title: Env. Specialist

Date: 7/24/2018 12:23:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401712402	PH F-18 Photo 1
401712405	PH F-18 Photo 2

Total Attach: 2 Files