

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2018

Submitted Date:

11/27/2018

Document Number:

688800361**FIELD INSPECTION FORM**Loc ID 335716 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilbourn, Don		dwilbourn@bry.com	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
Fischer, Alex		alex.fischer@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443326	LAND APPLICATION SITE	AC	09/25/2015		-	Berry F01 697	EI

General Comment:

On November 7, 2018 COGCC West Environmental Supervisor Alex Fischer and EPS Staff Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry F01 697 Land Application Site, Facility ID #44326. For the most recent field inspection report of this facility, please refer to document #688800193.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Location sign posted near entrance to pad.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted on location sign.		
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Sandbags stored in secondary containment berm.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/27/2018
Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Treatment	Adequate		
Comment	Please refer to REM #10044 for more information regarding this remediation project.			
Corrective Action				Date:

Spill/Remediation:

Comment:			
Corrective Action:		Date:	

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
				Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 7, 2018 COGCC West Environmental Supervisor Alex Fischer and EPS Staff Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry F01 697 Land Application Site, Facility ID #44326. For the most recent field inspection report of this facility, please refer to document #688800193. Berry representatives and their consultant were on site during this field inspection. Continue to remove liner pieces as they become exposed. The sandbags stored in the secondary containment area should be removed unless they are for use on this lease.	hughesjo	11/27/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401852132	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4656891
688800362	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4656888