

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2019

Submitted Date:

02/14/2019

Document Number:

674902570

**FIELD INSPECTION FORM**

Loc ID 451044 Inspector Name: Beam, Russell On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@crestonepr.com	<a href="#">ALL INSPECTIONS</a>

**General Comment:**

[This is a follow-up inspection to Field Inspection Report \(FIR\) Document #674902526 and in response to Field Inspection Report Resolution Document #401934548 stating that corrective actions have been performed.](#)

**Location Construction**

Location ID: 451044 CDP: \_\_\_\_\_

**Comment:** A disturbance area of approximately 11.85 acres was mapped on 2/13/2019 using a Trimble Juno 3B handheld device; this appears to be out of compliance with the approved Form 2A for the permitted disturbance area.

**Corrective Action:** Operator shall submit an Amended Form 2A (Document #400798140) for the modification and expansion of the Oil and Gas Location. The Form 2A shall be submitted within 30-days of receipt of this inspection document and the Form 2A must be considered complete per Rule 303.f. The Form 2A submission does not relieve the operator of potential enforcement action. **Date:** 03/16/2019

**Form 2A COAs:**

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater issues remain from previous inspection #674902526.](#)

Corrective Action: **Perform erosion repairs. Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Install or repair required BMPs per Rule 1002.f.**

Date: 02/06/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401940648	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735321">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735321</a>
674902585	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735318">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735318</a>