

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401945241

Date Received:

02/20/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51065

Name of Operator: LOEB LLC* HERMAN L

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Pelton, Shane	620-617-5870	shane@loeboil.com
Jesse Middagh	815-556-0756	jesse@loeboil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600612

Inspection Date: 01/31/2019

FIR Submit Date: 02/01/2019

FIR Status: _____

Inspected Operator Information:

Company Name: LOEB LLC* HERMAN L

Company Number: 51065

Address: P O BOX 838

City: LAWRENCEVILLE State: IL Zip: 62439

LOCATION - Location ID: 321669

Location Name: WHITE 'AM'-614S42W Number: 24SWNE County: CHEYENNE

Qtrqtr: SWNE Sec: 24 Twp: 14S Range: 42W Meridian: 6

Latitude: 38.822114 Longitude: -102.059833

FACILITY - API Number: 05-017-00 Facility ID: 207726

Facility Name: WHITE 'AM' Number: 1

Qtrqtr: SWNE Sec: 24 Twp: 14S Range: 42W Meridian: 6

Latitude: 38.822114 Longitude: -102.059833

CORRECTIVE ACTIONS:

1 CA# 122243

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 03/02/2019

Response: CA COMPLETED

Date of Completion: 02/19/2019

Operator Comment: Partially corrected - Plan is in place pending adequate weather and ground conditions. Hard cake build up around well head cannot be safely and properly removed until after ground thaws. Plan is to digout during upcoming spring season and replace with fresh soil / sand. Seeking extension of deadline to execute final and actual field corrective actions.

COGCC Decision: **Not Approved**

COGCC Representative: Operator is making request for extension of Corrective Action deadline after report has been publicly issued.

2 CA# 122244

Corrective Action: Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details. Date: 02/02/2019

Response: CA COMPLETED Date of Completion: 02/02/2019

Operator Comment: Vent valve was closed on 2/2/19, bull plug on valve missing. Well head was replumbed on 2/14/19 to replace leaking casing vent valve identified on follow-up inspection 2/13/19, and install new plug. No venting / leaks observed. Photo attached. Operator is taking necessary steps including data collection to seek request for venting from COGCC in near future.

COGCC Decision: Approved

COGCC Representative:

3 CA# 122245

Corrective Action: Install sign to comply with Rule 210.b. Date: 03/02/2019

Response: CA COMPLETED Date of Completion: 02/04/2019

Operator Comment: Updated contact information on signage. Photo attached.

COGCC Decision: Approved

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Two corrective actions fully implemented. Third corrective action is planned pending ground / weather conditions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jesse Middagh Signed: _____

Title: Manager; E&P Ops Date: 2/20/2019 10:34:47 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401945241	FIR RESOLUTION SUBMITTED
401945270	Contact Information updated on signage
401945279	New casing vent valve and plug installed

Total Attach: 3 Files