

GOLDEN EAGLE 30-02 API# 05-071-09854 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401783



PHOTO 1: THE UNUSED PARTS AROUND THE SEPARATOR HOUSE WERE REMOVED FROM LOCATION IN COMPLIANCE WITH RULE 603.F.

GOLDEN EAGLE 30-02 API# 05-071-09854 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401783



PHOTO 2: THE IMPACTED SOIL AROUND THE WELL HEAD AND ENGINE SKID WERE REMOVED FROM LOCATION IN COMPLIANCE WITH RULE 603.F.

GOLDEN EAGLE 30-02 API# 05-071-09854 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401783



PHOTO 3: THE IMPACTED SOIL AROUND THE WELL HEAD WAS REMOVED AND THE PACKINGS WERE REPLACED TO STOP THE WATER LEAK.

GOLDEN EAGLE 30-02 API# 05-071-09854 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 16, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401783



PHOTO 4: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED.