



00599457

MAR 04 1982
RECEIVED
MAR 8 1982

The Application(s) for Permit to Drill (OGCC Form 2) enclosed herewith cannot be processed at this time for the reason(s) stated below:

3/2/82

534-7544

Thomas W. Whittington

- ☒ No plugging bond attached
- ☐ No surface bond ☐ Bond not signed
- ☐ No filing fee (\$75) ☐ Filing fee check not signed
- ☐ Application for Permit to Drill (OGCC Form 2) not signed
- ☐ Letter of waiver from owners of offsetting lease(s)
- ☐ Location not in accordance with Rule 318 or Spacing Order(s)
- ☐ Location not clearly reported
- ☐ Incomplete item(s) number(s)
on Application to Drill (OGCC Form 2)
- ☐ Name of proposed objective horizon or geological formation
- ☒ Other INDICATE IF LANDOWNER IS A PARTY TO THE
LEASE, SEE ATTACHED. Done

Please correct and resubmit.

OIL & GAS CONSERVATION COMMISSION

BEST IMAGE
AVAILABLE