

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402039102

Date Received:

05/09/2019

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687904623

Inspection Date: 04/19/2019

FIR Submit Date: 04/19/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326067

Location Name: MW JOHNSON G A-M34N8W Number: 16NWNW County: LA PLATA

Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M

Latitude: 37.195509 Longitude: -107.727750

FACILITY - API Number: 05-067- -00 Facility ID: 215812

Facility Name: MW JOHNSON A Number: 1

Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M

Latitude: 37.195509 Longitude: -107.727750

CORRECTIVE ACTIONS:

1 ☒ CA# 124479

Corrective Action: Stop release immediately. Take necessary steps in engine repair or muffler reconfiguration and comply Rules 906 and 907

Date: _____

Response: CA COMPLETED

Date of Completion: 04/30/2019

Exhaust flex hose was found to have been damaged and cracked. A new hose was installed to prevent future

Operator
Comment: leaks.

COGCC Decision: Approved

COGCC
Representative:

2 ☒ CA# 124480

Corrective Action: Remove impacted material per Rules 907 and 1002.f., self inspect/take measures to prevent future breakdown of BMPs

Date: _____

Response: CA COMPLETED

Date of Completion: 04/30/2019

Operator
Comment: All impacted soils were excavated and taken to the BPX soil box for batch remediation at IEI in NM. Areas of excavation were backfilled with clean soils.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed on this location see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/9/2019 4:48:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402039102	FIR RESOLUTION SUBMITTED
402039137	Compliance follow up form

Total Attach: 2 Files