

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402178031

Date Received:  
09/17/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Abigail Wenk

7206446997

awenk@bisonog.com

Ariana Solis

7206446997

asolis@bisonog.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696200568

Inspection Date: 08/08/2019

FIR Submit Date: 08/09/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 455519

Location Name: Boomslang Fed 8-60 Number: 14B County: \_\_\_\_\_

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

### FACILITY - API Number: 05-123-00 Facility ID: 455519

Facility Name: Boomslang Fed 8-60 Number: 14B

Qtrqr: E2SE Sec: 14 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.659078 Longitude: -104.050458

### CORRECTIVE ACTIONS:

1 ☒ CA# 129086

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Sediment traps have been cleared, with a geotextile liner added under the rock aggregate. Straw wattle has been added to location to slow stormwater discharge.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 129087

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Culverts have had geotextile liner installed underneath aggregate. Straw wattle has been added to location to slow stormwater discharge.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 ☒ CA# 129088

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Hydromulch has been utilized at location along ditches and berms. Vertical tracking has been implemented at location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 ☒ CA# 129089

Corrective Action: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 08/09/2019

Response: CA COMPLETED

Date of Completion: 09/04/2019

Operator Comment: Vertical tracking has been corrected on location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 9/17/2019 3:39:43 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402178031	FIR RESOLUTION SUBMITTED
402179908	Corrective action photos

Total Attach: 2 Files