

FORM

6

Rev
05/18

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402272141

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 31257

Contact Name: Gene Fritzler

Name of Operator: FRITZLER RESOURCES INC

Phone: (970) 768-0845

Address: P O BOX 114

Fax: (866) 4374804

City: FORT MORGAN State: CO Zip: 80701

Email: gfritzler12@gmail.com

For "Intent" 24 hour notice required,

Name: _____

Tel: _____

COGCC contact:

Email: _____

API Number 05-123-11143-00

Well Name: LAW

Well Number: 1-17

Location: QtrQtr: NESW Section: 17 Township: 7N Range: 66W Meridian: 6

County: WELD

Federal, Indian or State Lease Number: 55686

Field Name: COALBANK CREEK

Field Number: 11449

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.573082

Longitude: -104.804544

GPS Data:

Date of Measurement: 06/03/2008

PDOP Reading: 2.1

GPS Instrument Operator's Name: Gene Fritzler, PE

Reason for Abandonment:

☐ Dry☐ Production Sub-economic☐ Mechanical Problems☐ Other _____Casing to be pulled: ☐ Yes☐ No

Estimated Depth: _____

Fish in Hole: ☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☐ No

If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	7210	7470			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/2	8+5/8	24	327	350	327	0	VISU
1ST	7+7/8	4+1/2	16.6	7,637	625	7,560	6,322	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7125 with 70 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>161</u> sks cmt from <u>377</u> ft. to <u>0</u> ft.	Plug Type: <u>ANNULUS</u>	Plug Tagged: <input type="checkbox"/>
Set <u>20</u> sks cmt from <u>900</u> ft. to <u>730</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set <u>20</u> sks cmt from <u>3700</u> ft. to <u>3530</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set _____ sks cmt from _____ ft. to _____ ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____ sks cmt from _____ ft. to _____ ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at 3803 ft. with 80 sacks. Leave at least 100 ft. in casing 3700 CICR Depth

Perforate and squeeze at 1000 ft. with 80 sacks. Leave at least 100 ft. in casing 900 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 161 sacks half in. half out surface casing from 377 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. _____ inch casing Cut and Cap Date: 10/08/2019
of _____

*Wireline Contractor: KLX Energy Services *Cementing Contractor: Yetter Well Serv & Cementers

Type of Cement and Additives Used: Type I - II , 15# to 15.8#

Flowline/Pipeline has been abandoned per Rule 1105 ☒ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

The additional CICR at 900 ft was approved by Dirk.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Gene Fritzler

Title: VP Date: _____ Email: gfritzler12@gmail.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402272200	CEMENT JOB SUMMARY
402272202	OTHER
402272203	WIRELINER JOB SUMMARY
402272205	OTHER
402272209	OTHER
402272211	OTHER
402272212	OTHER
402272213	OTHER
402273462	WELLBORE DIAGRAM

Total Attach: 9 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)