

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402127113

Date Received:

07/31/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900464

Inspection Date: 06/19/2019

FIR Submit Date: 07/08/2019

FIR Status: _____

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 428191

Location Name: Hughes 11-90-26 Number: 2 County: GUNNISON

Qtrqr: LOT 6 Sec: 26 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.068330 Longitude: -107.419290

FACILITY - API Number: 05-051- -00 Facility ID: 428189

Facility Name: HUGHES 11-90-26 Number: 2

Qtrqr: LOT 6 Sec: 26 Twp: 11S Range: 90W Meridian: 6

Latitude: 39.068330 Longitude: -107.419290

CORRECTIVE ACTIONS:

1 ☒ CA# 126785

Corrective Action: Stormwater controls need to be installed along the access using good engineering practices such as those described in CDOT manuals for erosion and stormwater control. Erosion along the access road needs to be stabilized. This is the second corrective action for erosion along the access road.

Date: 07/22/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: This region received an abnormally large amount of snowfall, which resulted in several very large snowmelt events. The installed SW controls functioned as designed for a normal year. All SW controls that needed maintenance have been maintained. As with all areas with steep cut slopes, SW control maintenance is an ongoing process. The cut slopes are scheduled for hydromulch and seeding in a few weeks. Please note the first CA was on 12/5/17; the follow up inspection indicated no stormwater road issues on the 7/25/18 inspection.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed: _____

Title: Env & Reg Manager

Date: 7/31/2019 1:28:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402127113	FIR RESOLUTION SUBMITTED
402127197	CA Photos

Total Attach: 2 Files