

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2020

Submitted Date:

05/08/2020

Document Number:

688000447

FIELD INSPECTION FORM

Loc ID 317166 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 94300
Name of Operator: WARD & SON* ALFRED
Address: P O BOX 737
City: OGALLALLA State: NE Zip: 69153

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
Leonard, Mike	719-343-0130	mike.leonard@state.co.us	
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Axelson, John		john.axelson@state.co.us	
Marette, Brandon	303-291-7327	brandon.marette@state.co.us	CPW NE Energy Liaison

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117639	PIT	AC			-	WRIGHT 31-1	EI

General Comment:

Environmental inspection related to recent release of crude oil to the produced water pit (ID 117639). Multiple bird fatalities were found associated with the oil on the pit. A vacuum truck was on site at the time of inspection removing the remaining oil from the produced water pit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 117639 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Landfarmed soil associated with Rem #10196 have been removed from the location and the former oil skim pit has been backfilled.

Corrective Action: Provide soil disposal manifests and request NFA status on a supplemental eForm 27 as per the comment on Form 27 Doc. No. 401775698, 10/9/2018.

Date: 05/29/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 117639 Lat: 39.827626 Long: -103.350026

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Recent release of oil has at some point covered the entire produced water pit and created a ring of oil stained soil on the pit berms.

Corrective Action

Remove the oil stained soil from the pit berms and provide clean pit berm photographs and soil disposal manifests on a supplemental eForm 19.

Date: 05/29/2020

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000448	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146076