

Well Name: Bull Creek Federal 1 **API #** 05-007-06122
Inspection Number: 693901794

Corrective Action: Erosional channels are forming within the northeastern cut-slope. Sediment deposition observed at the toe of the slope.
Stormwater controls need to be installed to stabilize erosion.

Correction Action Due: 6/18/2020

Action Completed: 5/27/2020

Action Taken: Installed wattles on slope and rock dams along erosion channels.

