

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402289982

Date Received:
01/20/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679602128

Inspection Date: 01/07/2020

FIR Submit Date: 01/07/2020

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 432327

Location Name: Triangle Number: 6-22 County: _____

Qtrqr: SENW Sec: 22 Twp: 7N Range: 65W Meridian: 6

Latitude: 40.561846 Longitude: -104.650390

FACILITY - API Number: 05-123-00 Facility ID: 432327

Facility Name: Triangle Number: 6-22

Qtrqr: SENW Sec: 22 Twp: 7N Range: 65W Meridian: 6

Latitude: 40.561846 Longitude: -104.650390

CORRECTIVE ACTIONS:

1 CA# 135747

Corrective Action: Comply with Rule 603.f.

Date: 02/07/2020

Response: CA COMPLETED

Date of Completion: 01/20/2020

Operator
Comment:

The risers are in "Out-of-Service" status and in compliance with Rule 1101.a.(3). These risers have been:
• Isolated from all oil, condensate, produced water, or natural gas,
• Evacuated and purged of all fluids, and
• OOSLAT has been applied.
CA's completed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 135748

Corrective Action: Comply with Rule 603.f.

Date: 11/28/2019

Response: CA COMPLETED

Date of Completion: 11/22/2019

Operator
Comment:

The risers are in "Out-of-Service" status and in compliance with Rule 1101.a.(3). These risers have been:

- Isolated from all oil, condensate, produced water, or natural gas,
- Evacuated and purged of all fluids, and
- OOSLAT has been applied.

CA's completed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The risers are in "Out-of-Service" status and in compliance with Rule 1101.a.(3). These risers have been:

- Isolated from all oil, condensate, produced water, or natural gas,
- Evacuated and purged of all fluids, and
- OOSLAT has been applied.

CA's completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: EHS Coordinator

Date: 1/20/2020 3:41:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402289982	FIR RESOLUTION FORM
402449634	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files