Inspector Name: COSTA, RYAN

FORM INSP

> Rev X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 08/11/2020
Submitted Date:

Document Number: 690200518

08/14/2020

## FIELD INSPECTION FORM

Loc ID	Inspector Nam	ne:	On-Site	Inspection		Status Summary:	
324930	·		A Doc Num:		$\overline{f X}$ THIS IS A FOLLOW UP INSPECTIO	N	
Operator Information:						$\overline{f X}$ FOLLOW UP INSPECTION REQUIR	ED
OGCC Ope	erator Number:	17180			NO FOLLOW UP INSPECTION REQ	UIRED	
Name of Op	perator: CITATION	OIL & GA	S CORP		Findings:		
۸ ما ما معمد .	4077 CUTTEN DD				3 Number of Comments		
Address: 1	4077 CUTTEN RD	1				1 Number of Corrective Actions	
City:	HOUSTON	State:	TX	Zip:7726	69	Corrective Action Response Requested	
						ANY CORRECTIVE ACTION(S) FRO PREVIOUS INSPECTIONS THAT HA BEEN ADDRESSED ARE STILL AP	AVE NOT
Contact Inf	formation:						
Contact Name		Phoi	ne	Email		Comment	
WARD SHARON			sward@cogc.com		om		
Trujillo, Aaron			aaron.trujillo@state.co.u		state.co.us		
Inspected I	Facilities:						
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213484	WELL	PA	07/10/2012	GW	063-0604	HICKS B 1	RI
	onment:  ollow up of the prevous corrective action				, #69620070	2.	

See attached photos and additional details within this report.

Inspector Name: COSTA, RYAN

Reclamation - Storm Water - Pit							
Interim Reclamation:							
Date Interim Recl							
Land Use:	Land Use:						
Comment:							
1002 SITE PREPAR	ATION AND STABILIZATION						
1002a. FENCIN	G						
Comment							
Corrective Action		Date					
1002b. SOIL RE	MOVAL AND						
Comment							
Corrective Action		Date					
1002c. PROTEC	CTION OF SOILS						
Comment							
Corrective Action		Date					
1002E. SURFAC	CE DISTRURBANCE MINIMIZATION						
Comment							
Corrective Action		Date					
1003a. Waste a	nd Debris removed?						
Comment							
Corrective Action		Date					
Unused	or unneeded equipment onsite?						
Comment							
Corrective Action		Date					
Pit, cel	lars, rat holes and other bores closed?						
Comment [							
Corrective Action		Date					
Guy line	anchors marked?						
Comment							
Corrective Action		Date					

Inspector Name: COSTA, RYAN Production areas stabilized? 1003b. Area no longer in use? 1003c. Compacted areas have been cross ripped? Subsidence over on drill pit? 1003d. Drilling pit closed? Cuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Production areas have been stabilized? Segregated soils have been replaced? RESTORATION AND REVEGETATION Cropland Top soil replaced Perennial forage re-established Recontoured Non-Cropland Recontoured \_\_\_\_ 80% Revegetation Top soil replaced 1003e. INTERIM VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVEF VEGETATIVE COVER 1003 f. Weeds Noxious weeds? Comment Corrective Action Overall Interim Reclamation Final Reclamation/ Abandoned Location: Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Well plugged Pit mouse/rat holes, cellars backfilled No disturbance /Location never built Debris removed Contoured \_\_\_\_ Culverts removed \_\_\_\_ Access Roads Regraded Gravel removed Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Compaction alleviation Dust and erosion control Cropland: perennial forage Fail Non cropland: Revegetated 80% Weeds present Subsidence 1004.d. FINAL VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER \_\_\_\_\_ Comment:

Inspector Name: COSTA, RYAN

The pipe riser remains at the location and is interfering with farming operations. All equipment should have been removed within three months of plugging the well. Previous corrective action has not been performed to remove the pipe riser. Previous inspection also documented that the crop had failed to establish in areas of the location. There was no crop growth during this inspection to evaluate crop establishment however, there are multiple areas of concern that are shown in the aerial image that need to be evaluated for crop establishment.

Unable to find evidence that additional reclamation has been conducted in accordance with rule 1004 and per corrective actions. Original corrective action and date remains applicable.

Corrective Action:

Comply with 1004 Rules.

Remove riser and perform additional reclamation activities in accordance to COGCC 1000 series rules and requirements. To allow Citation time to 1) determine issues on location hindering crop establishment/reclamation, 2) collaborate with the surface owner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production, and 3) collaborate with the midstream company to remove the riser remaining on the location, all reclamation activities shall be completed no later than 10/31/2018.

Overall Final Reclamation Fail Well Release on Active Location Multi-Well Location

COGCC Comments						
Comment	User	Date				
Ongoing 1004 Final reclamation compliance issues have been documented since 2013. Non-Compliance issues will be refered to enforcement.	CostaR	08/14/2020				

## **Attached Documents**

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
402466902	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5224062
690200519	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5224061

Date

10/31/2018