

# OIL AND GAS CONSERVATION COMMISSION DEPARTMENT OF NATURAL RESOURCES OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.



00244643

MAR 9 1987

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. Fee	
2. NAME OF OPERATOR Bass Enterprises Production Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1099 18th St., Suite 1600 Denver, CO 80202		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2380' FSL and 2271' FEL, NW NW SE Sec. 9, T11N, R68W At proposed prod. zone		8. FARM OR LEASE NAME Meadow Springs	
14. PERMIT NO. 85-86		9. WELL NO. 9-31	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL=6058		10. FIELD AND POOL, OR WILDCAT Meadow Springs "J" ✓	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 9-11N-68W	
		12. COUNTY Larimer	13. STATE Colorado

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work \_\_\_\_\_

It is intended to plug and abandon the well as follows:

1. MIRU Donnelly Casing & Pulling.
2. TOOH & LD rods and tbg.
3. Dump bail sand in 5-1/2" csg to 7800' (Perfs located @ 7866-7872' and 7883-7894').
4. Dump bail 5 sx cement on top of sand.
5. Load hole. Shoot off 5-1/2" csg.
6. TOOH w/recoverable csg. Set 25 sx cement plug over stub ✓ Set 10 sx cement plug @ surface.
7. Cut off csg head. Weld on cap.
8. Rehab and reseed location.
9. SEND FA WHEN COMPLETED.

+20SX @ base of surface pipe (671')  
BB

FOR OFFICE USE ONLY
ET
FE
UC
SE

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Asst. Production Foreman

DATE March 5, 1987

(This space for Federal or State office use)

APPROVED BY [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

SUPR. PETROLEUM ENGINEER  
TITLE Oil & Gas Cons. Comm.

DATE MAR 11 1987