Inspector Name: BROWNING, CHUCK

FORM INSP

Rev X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 11/19/2020
Submitted Date:

<u>11/24/2020</u> Document Number: <u>693802540</u>

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site In			Inspection			Stat	us Summary:				
322107	BROWNING,	CHUCK		A Doc Num:	:			THIS IS A FOLLOW UP INSPECT	TION		
Operator In	formation:						X	FOLLOW UP INSPECTION REQU	JIRED		
OGCC One	rator Number:	10754						NO FOLLOW UP INSPECTION R	EQUIRED		
·	erator: FOUR CO		MEDCY I I C				Find	lings:			
name of Op	erator. FOUR CO	KINEKS E	NERGT LLC				9				
Address: 5	31 E 770 N						4				
City:	OREM	State:	UT	Zip:	8409	97		Corrective Action Response Requester			
				-			1				
							ĺ	ANY CORRECTIVE ACTION(S) F PREVIOUS INSPECTIONS THAT	HAVE NOT		
								BEEN ADDRESSED ARE STILL	APPLICABLE		
Contact Inf	ormation:										
Contact Name		Phor	ne	Email			Comment				
Williams, Larry		(801) 657-5780	larry@thesummitcompanies.com		es.c					
Pesicka, Conor			conor.pesicka@state.co.us			ıs					
Labowskie, Steve				steve.labowskie@state.c			o.us				
Browning, Chuck		970-	433-4139	3-4139 chuck.brow		g@state.co	us.	Field Inspector	Field Inspector		
Rabinowitz, Daniel		970-	385-1363	drabinow@blm.gov		Durango					
Telecky, Barbara				btelecky@blm.gov				Durango			
,			dnr_cogccengineering@state.co.us			tate.					
Inspected F	acilities:										
Facility ID	Туре	Status	Status Date	Well C	Well Class API Num			Facility Name	Insp Status		
208980	WELL	SI	10/01/2017	GW		033-0608	35	WILLIE WASCHKE 4-17	TA		
General Co	mment:			-							
COGCC st	aff performed a fie	ld inspect	ion on 11/19/20	120							

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Inspector Name: BROWNING, CHUCK

<u>Location</u>									
Lease Road:									
Туре	Access								
comment:									
Corrective ActionL		Date:							
Туре	Main	Main							
comment:									
Corrective ActionL	nL Date:								
Overall Good: 🔀									
Signs/Marker:									
Туре	TANK LABELS/PLACA	RDS							
Comment:	Sign or label not posted small to read at distance	or information inac or installed in place	ccurate on tanks or c ce where not visible.	containers or s	sign/label too				
Corrective Action:	Install sign to comply w	th Rule 210.d.				Date:	12/31/2020		
Туре	BATTERY								
Comment:									
Corrective Action:						Date:			
Emergency Contact I	Number:								
Comment:	801-657-5780 or 435-2	79-7144							
Corrective Action	:					Date:			
Good Housekeepin	g <u>:</u>								
Туре	WEEDS								
Comment:	Weeds								
Corrective Action:	Comply with Rule 603.f . Date: <u>12/05/2020</u>								
Overall Good: 🔀									
Spills:									
Туре	Area	Volume							
In Containment: I	No	•							
Comment:									
Multilple Spills and Releases?									
Equipment:							corrective date		
Type: Bradenhead		#							
Comment	: Bradenhead not plumb	ed to surface							
Corrective Action: Comply with rule 341.a.2 Date: 12/31/2020							12/31/2020		
Type: Bird Protectors # 1									
Comment	:								
Corrective Action: Date:									
Tanks and Berms:									
Contents	# Capacity	Туре		Tank ID	SE GPS				

Inspector Name: BROWNING, CHUCK CRUDE OIL 2 400 BBLS STEEL AST 37.636561,-108.962439 Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) <u>Berms</u> Capacity Туре Permeability (Wall) Permeability (Base) Maintenance Earth Adequate Walls Sufficent Base Sufficient Adequate Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

					<u>Inspecte</u>	d Facilities				
acility ID: _	208980	Туре	e: WELL	L	API Number:	033-06085	Status:	SI	Insp. Status:	TA
					<u>ldle</u>	<u>Well</u>				
Purpos	e: 🔲 Sh	nut In	▼ Tempor	rarily Aba	ndoned	Reminder:				
Comment: Well shut in 8/2016. No MIT on record. Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.										
Corrective	Action:		uccessful me day CA time t	chanical the well n	integrity test. nust be plugge	If a successful MI d within 3 months	T can not be per Rule 326	performed and 208.	Date: 12/31/	2020

Inspector Name: BROWNING, CHUCK

Reclamation - Storm Water - Pit								
Storm Water:								
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment		
Compaction	Pass	Compaction	Pass					
Comment:								
Corrective Action:					Date:			
Pits: NO SURFACE INDICATION OF PIT								

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num Description		URL				
402540061	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297996				
693802554	Inspection photos 11/19/2020	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5297975				

Date Run: 12/1/2020 Doc [#693802540] Page 5 of 5