


Issue Report

Trade Winds 5-21, 061-06895

Report created on January 27, 2021

Captured: January 22, 2021



Type	Count
Erosion	3

No.	Summary	Type	Created	Status
3	Soil has blown out of road and is drifting around minimal vegetation.	Erosion	Jan 27, 2021 at 3:55pm	Open
2	Soil drifting around minimal vegetation.	Erosion	Jan 27, 2021 at 3:54pm	Open
1	Area has minimal vegetation with wind erosion.	Erosion	Jan 27, 2021 at 3:52pm	Open

Erosion

No. 1 OPEN

Captured: Jan 22, 2021 at 9:46am

**Type**

Erosion

Lat/Long

38.47789, -102.68002

Summary

Area has minimal vegetation with wind erosion.

Created

Jan 27, 2021 at 3:52pm by Craig Quint

No. 2 OPEN**Captured: Jan 22, 2021 at 9:46am****Type**
Erosion**Lat/Long**
38.47721, -102.68049**Summary**
Soil drifting around minimal vegetation.**Created**
Jan 27, 2021 at 3:54pm by Craig Quint

No. 3 OPEN

Captured: Jan 22, 2021 at 9:46am



Type
Erosion

Lat/Long
38.47784, -102.68064

Summary
Soil has blown out of road and is drifting around minimal vegetation.

Created
Jan 27, 2021 at 3:55pm by Craig Quint

