

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2021

Submitted Date:

05/20/2021

Document Number:

696303268

FIELD INSPECTION FORM

Loc ID 327432 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	
Smith, Chris	(970) 330-7034	smithenergy@live.com	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246888	WELL	SI	06/01/2018	GW	123-14685	WELD WEITZEL 5-33	SI

General Comment:

[Follow-Up Inspection to FIR 696300753 dated 10.24.2019](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds at Wellhead, see photo		
Corrective Action:	Comply with Rule 606		Date: 11/25/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead does NOT appear to be plumbed to surface		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 05/31/2021
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 246888 Type: WELL API Number: 123-14685 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Since 06.01.2018. No MIT on Record. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 06/18/2021

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				
Comment: <input style="width: 90%;" type="text" value="Pasture/CRP"/>						Date: _____
Corrective Action: <input style="width: 90%;" type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 05/18/2021 at approximately 12:29 I, Inspector Erica Petrie, conducted a Field Inspection at Smith Energy Corp, Weld Weitzel 5-33, at Location #327432 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds at Wellhead. See Photos 1. Comply with Rule 603.f. Corrective Action date 11.25.2019</p> <p>SI - Since 06.01.2018. No MIT on Record. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.</p> <p>Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Corrective Action Date 06.18.2021 or as determined by COGCC Engineering Department</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	petrie	05/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303269	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434706