

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402945632

Date Received:

02/02/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

970-285-9377

COGCCInspectionReports@terraep.com

COGCC

aaron.trujillo@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703786

Inspection Date: 01/26/2022

FIR Submit Date: 01/31/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335263

Location Name: CLOUGH FEDERAL-66S94W Number: 20SENE County: \_\_\_\_\_

Qtrqr: SENE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.513829 Longitude: -107.906821

FACILITY - API Number: 05-045-00 Facility ID: 335263

Facility Name: CLOUGH FEDERAL-66S94W Number: 20SENE

Qtrqr: SENE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.513829 Longitude: -107.906821

CORRECTIVE ACTIONS:

3 CA# 159438

Corrective Action: Install or repair required BMPs

Date: 03/31/2022

Response: CA COMPLETED

Date of Completion: 02/02/2022

Operator Comment: Road and crossing are maintained as needed. Runoff water noted in inspection photos is coming from drainage areas above the water crossing is laden with naturally occurring sediment that is coming from areas above the crossing. The road and crossing are constructed in alluvial deposits with a high rock content which helps to stabilize the crossing and prevents down-cutting by occasional traffic. The crossing and occasional traffic are not contributing a significant source of sediment to the snow melt runoff that is running in this drainage.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

|  |
|--|
|  |
|--|

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action has been addressed. TEP staff will meet on-site to evaluate further is requested.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP ENV

Date: 2/2/2022 4:29:49 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <b><u>Document Number</u></b> | <b><u>Description</u></b> |
|-------------------------------|---------------------------|
|-------------------------------|---------------------------|

|  |  |
|--|--|
|  |  |
|--|--|

Total Attach: 0 Files