

RECEIVED

JUL 1 1980

OGR

RE



00242428

OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES

THE STATE OF COLORADO

... duplicate for Patented and Federal lands.
File in triplicate for State lands.

COLO. OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Dry</u>		5. LEASE DESIGNATION AND SERIAL NO.	
2. NAME OF OPERATOR <u>NORTH PARK ENERGY, INC.</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR <u>95 Circle Dr. Ft. Collins, Co 80524</u>		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>NE$\frac{1}{4}$ NW$\frac{1}{4}$</u> At proposed prod. zone		8. FARM OR LEASE NAME <u>Elevins "A" Streit Ranch</u>	
14. PERMIT NO. <u>79638</u>		9. WELL NO. <u>SR 5</u>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>8055'</u>		10. FIELD AND POOL, OR WILDCAT <u>Canadian River</u>	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 11, T9N R78W</u>	
		12. COUNTY <u>Jackson</u>	13. STATE <u>Colo</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON ☐CHANGE PLANS ☐☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 7-10-80

1. Run tubing to T.D. 450'
2. Pump hole full of cement - 50 sacks
3. Cut surface casing 3' below surface ground level as per request of Land owners because land is hay meadow.
4. Recede and level location.

DVR	<input checked="" type="checkbox"/>
FJP	<input checked="" type="checkbox"/>
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
RLS	<input type="checkbox"/>
OGM	<input type="checkbox"/>

18. I hereby certify that the foregoing is true and correct.

SIGNED

Bertrude Streit

TITLE

Secretary

DATE

6-30-80

(This space for Federal or State office use)

APPROVED BY

W. Rogers

TITLE

DIRECTOR
O & G CONS. COMM.

DATE

JUL 2 1980

CONDITIONS OF APPROVAL, IF ANY:

File 2