

TEP
Ferguson
Location # 335386



location



location



TEP
Ferguson
Location # 335386



location



location

TEP
Ferguson
Location # 335386



Stored equipment (ECD is disconnected from tanks and gas) from recent inspection (5/17/2022)



Stored equipment (ECD is disconnected from tanks and gas) From previous inspection (10/14/2021)

TEP
Ferguson
Location # 335386



Lack of stabilization/erosion with sediment migration choking out vegetation



Lack of stabilization/erosion with sediment migration choking out vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Ferguson
Location # 335386



Lack of stabilization/erosion with sediment migration choking out vegetation



Lack of stabilization/erosion with sediment migration choking out vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Ferguson
Location # 335386



Lack of stabilization/erosion with sediment migration choking out vegetation



Lack of stabilization/erosion with sediment migration choking out vegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Ferguson
Location # 335386



**Lack of stabilization/erosion with sediment
migration choking out vegetation**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources