

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403107791

Date Received:

07/18/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Andrew Price

Phone

918-965-0044

Email

aprice@arkomaops.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500202

Inspection Date: 07/08/2022

FIR Submit Date: 07/08/2022

FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC

Company Number: 10766

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 311897

Location Name: IGW-N33N8W Number: 7NWNE County: LA PLATA

Qtrqr: NWNE Sec: 7 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122540 Longitude: -107.755140

FACILITY - API Number: 05-067-00 Facility ID: 216577

Facility Name: FASSETT Number: 1-A

Qtrqr: NWNE Sec: 7 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122540 Longitude: -107.755140

CORRECTIVE ACTIONS:

1 ☒ CA# 163208

Corrective Action: Out of service flowlines must be tagged and identified per rule 1101.(3)

Date: 07/24/2022

Response: CA COMPLETED

Date of Completion: 07/15/2022

Operator Comment: Out of service flowlines are tagged and locked out.

COGCC Decision: Approved pending re-inspection

CA from previous inspection Doc# 702500202 has been satisfactorily completed.

COGCC
Representative:

2 ☒ CA# 163209

Corrective Action: Remove oily residue and impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/23/2022

Response: CA COMPLETED

Date of Completion: 07/15/2022

Operator Comment: Removed contaminated soil around pumping unit and scrubbed skid with degreaser, power-washed, etc. but stain would not come out. Disposed of contaminated soil and will keep working on stain.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500202 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed:

Title: Engineering Analyst

Date: 7/18/2022 9:10:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403107791	FIR RESOLUTION SUBMITTED
403108192	Photos

Total Attach: 2 Files