

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2022

Submitted Date:

08/29/2022

Document Number:

679605037**FIELD INSPECTION FORM**Loc ID 327053 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 88265Name of Operator: TIGGES OIL LLCAddress: 12406 WCR 64 1/2City: GREELEY State: CO Zip: 80631**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jesse.tigges@gmail.com	
Tigges, Kenneth	970-396-8381	levi.tigges@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
56731	WELL	SI	02/01/2022	OW	123-14072	TIGGES 3-31B	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign does not reflect correct wellhead name. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/09/2021

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil at wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.		Date: 06/09/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	56731	Type:	WELL	API Number:	123-14072	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder: EQUIPMENT PRESENT/DISCONNECTED									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/>									
Date: <input type="text"/>									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679604114 AND NOAV DOC#: 402859333. 2 out of 7 previous corrective actions assigned to this location remain unresolved. A Form 6(N) (in process) is also in the well file, and it appears the operator has removed most of the production equipment from location. Review narrative below for more details.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Friday, August 26, 2022 at approximately 08:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at TIGGES 3-31B (Tigges Oil LLC), at location #: 327053 in WELD COUNTY Colorado. While there, I observed a TA'd wellhead. During this inspection the following possible compliance issues were observed: 1. Wellhead sign displays incorrect wellhead name. Install sign to comply with Rule 605.d. (Corrective Action Date: June 9, 2021) See attached photo #1. 2. It appears to be stained soil at wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: June 9, 2021) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	08/29/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403149604	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5841810
679605038	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5841807