



RECEIVED

JAN 23 1973

OIL &amp; GAS CONSERVATION

January 22, 1973

RE: Completion Forms, #1 E. Deakins  
NE $\frac{1}{4}$ NW $\frac{1}{4}$  Sec. 23, T-6-N, R-90-W,  
Moffat County, Colorado  
Buck Peak Field

Mr. D. V. Rogers, Director  
State of Colorado, Dept. of Natural Resources  
Oil and Gas Conservation Commission  
Room 237 Columbine Building  
1845 Sherman Street  
Denver, Colorado 80203

Dear Mr. Rogers:

We did drill the #1 Deakins Well which is almost non-commercial as the well is only making about 20 BOPD. The reason we have never filed the well completion report is that we fractured this well with hundreds of barrels of oil and so far we have not recovered all of the load oil and we cannot ask Mountain Fuel Supply Company for an assignment of the Deakins lease until the well starts making new oil after recovering all of its load oil.

Based on the present rate of production, it will be approximately one more month before we recover all the load oil and hopefully, the well will continue to produce at 20 odd barrels per day and we shall then promptly file our well completion report and request an assignment from Mountain Fuel for the Deakins lease. We trust the above will explain the delay and we thank you for your cooperation.

Yours very truly,

TREND EXPLORATION LIMITED

Glenn A. Dow  
Vice President

GAD/dg

use #4