

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2023

Submitted Date:

03/23/2023

Document Number:

690204004

**FIELD INSPECTION FORM**

Loc ID 308888 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10351  
Name of Operator: WAPITI OPERATING LLC  
Address: 1310 W SAM HOUSTON PKWY N  
City: HOUSTON State: TX Zip: 77043

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Madison, Randy		rmadison@wapitienergy.com	
Mattorano, Michael		mmattorano@wapitienergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284295	WELL	PR	06/14/2006	CBM	071-08769	VPR C 125	RI
308888	LOCATION	AC			-	VPR C-635S67W 13SWNE	RI

**General Comment:**

This is a follow up of the previous reclamation inspections; #690201863, #690202101, #690202740, #690202865, #690203037, #690203239, #690203448, #690203659. The corrective action of the previous inspections has not been completed. See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the main road in the canyon traveling to the location. There are multiple culverts filled in with sediment directing stormwater down the road causing erosion. Areas of erosion need to be repaired and stabilized. Previous corrective action was not completed. This is the ninth notice documenting this issue. Corrective action must be performed immediately.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690204005	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6060122">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6060122</a>