

Inspection Photos

3/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335793

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 1: Photos 1-2 taken from the working pad area of the Location. Photos examples showing BMPs, including vehicle tracking control measures, remain missing or insufficient to minimize erosion, degradation, tracking and sediment transport during wet conditions. Regrading alone is inadequate to address tracking and stabilization issues. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 3: Photo shows ditch along access road has filled with sediment: BMP no longer in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 4: Photos 4-5 examples showing rock-sock BMPs within the ditch along the access road are no longer in proper functioning condition, and is now debris.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 6: Photos 6- 8 taken from the access road. Photos examples showing BMPs, including vehicle tracking control measures, remain missing or insufficient to minimize erosion, degradation, tracking and sediment transport during wet conditions. Regrading alone is inadequate to address tracking and stabilization issues. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 7: See comments under photo 6. 6 foot measuring stick used for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 8: See comments under photo 6.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335793



Photo 9: Photos show secondary containment at the tank battery remains inadequate to contain a spill.