

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403364445

Date Received:

04/04/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kellerby, Shaun

shaun.kellerby@state.co.us

Heil, John

john.heil@state.co.us

Depaolo, Corey

corey.depaolo@state.co.us

TEP

COGCCInspectionReports@terraep.com

Arauz, Steven

steven.arauza@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 708900147

Inspection Date: 03/23/2023

FIR Submit Date: 03/23/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 439173

Location Name: Youberg RU Number: 44-7 County: GARFIELD

Qtrqr: SESE Sec: 7 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.454903 Longitude: -107.810837

FACILITY - API Number: 05-045-00 Facility ID: 439165

Facility Name: Youberg RU Number: 532-7

Qtrqr: SESE Sec: 7 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.454903 Longitude: -107.810837

CORRECTIVE ACTIONS:

1 CA# 168490

Corrective Action: Operators will ensure that E&P Waste is properly stored, handled, transported, treated, recycled, or disposed

Date: 03/25/2023

Response: CA COMPLETED

Date of Completion: 03/24/2023

Operator Comment: A blower motor on one of the large volume tanks recently went out had to be replaced. To accomplish this task, the tank was pumped empty, and the bladder was deflated for a couple of days. While the tank was deflated, it snowed a few inches and snow melted inside the containment. Snow melt water came into contact with a small amount residue from an air flap on the top of the bladder. The residue and snow melt water were wholly contained within the secondary containment structure. The blower motor has since been replaced and the residue and snow melt water have been pumped out of the containment structure. TEP deployed a vac-truck and hot water to clean out the residue from inside the containment structure. The amount of residue that came into contact with the snow melt water was estimated to be less than 1 bbl and did not exceed any of the reporting thresholds per Rule 912.b, therefore, this was not a reportable release.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 168491

Corrective Action: Add required info to tank labels.

Date: 05/22/2023

Response: CA COMPLETED

Date of Completion: 04/03/2023

Operator Comment: Information has been added to tank labels as needed.

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 168493

Corrective Action: Operators will prevent & minimize adverse impacts to wildlife resources.

Date: 03/30/2023

Response: CA COMPLETED

Date of Completion: 03/29/2023

Operator Comment: Bird cone has been added.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Action numbers #168490, #168491, #168493 have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 4/4/2023 12:13:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files