

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2023

Submitted Date:

07/05/2023

Document Number:

694100116

FIELD INSPECTION FORM

Loc ID 456832 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
,		cogccinspection@pdce.com	All Inspections
Liesenfeld, Zack		Zack.Liesenfeld@pdce.com	

General Comment:

This is an environmental inspection for Spill ID: 483473 PDC Bost Farms - completions. Any corrective actions from previous inspections that have not been addressed are still applicable. There were contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☒

Spills:

Type	Area	Volume		
In Containment: No				
Comment: No spills on location.				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 7/12/2023 Doc [#694100116]

Page 2 of 4

Location Construction

Location ID: 456832 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
_____	_____	_____	_____

Comments: Erosion BMPs: Soil stock pile on location is not lined or contained within a wattle. Install necessary bmps to prevent offsite erosion.

Other BMPs: _____

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/12/2023
3**Comment:** Rutting and drainage issues on pad location. Affected areas need to be regraded.**Corrective Action:** Surface regrading needed. Install or repair required BMPs per Rule 1002.f.(2)C**Date:** 07/12/2023**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403453881	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169950
694100118	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169931