

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107544

### FIELD INSPECTION FORM

Loc ID 331279 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 65110  
Name of Operator: O'BRIEN ENERGY RESOURCES CORP  
Address: 18 CONGRESS ST STE 207  
City: PORTSMOUTH State: NH Zip: 03801

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260833	WELL	TA	07/30/2020	GW	123-20424	LOST CREEK O'BRIEN 3-20	TA

**General Comment:**

This is a follow up to prior inspection document #699107158. CA's were not corrected.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	well need to be fixed in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation around the well needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel Fence needs to be fixed. See attached photo		
Corrective Action:	Comply with the fencing requirements per the 1002a rules.	Date:	09/22/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 260833 Type: WELL API Number: 123-20424 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A  
No FIRR was submitted.

Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.

Date: 10/13/2023

**BradenHead**

Date of Last Brhd Test: 11/27/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #403257019 indicates it was last tested on 12/8/20.

09/22/2023

Corrective Action: Submit reports as per Rule 419.

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 10/9/23 at approximately 0913hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107158 at Lost Creek O'Brien 3-20 of O'Brien Energy Resources Corp. API #05-123-20424 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Overgrown vegetation around the well needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23 Panel Fence needs to be fixed. Comply with the fencing requirements per the 1002a rules. With a Corrective Action date of 9/22/23 No updated annual BH test on file. Submit reports. Form 17 #403257019 indicates it was last tested on 12/8/20. Submit reports as per Rule 419. With a Corrective Action date of 9/22/23 No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23 No CA's were corrected A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	10/11/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403557336	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281157</a>
699107545	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281129">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281129</a>