

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/11/2023

Document Number:

699107546

FIELD INSPECTION FORMLoc ID 331882 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joseph	603-427-2099 x111	joeforma@obenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267813	WELL	PR	03/01/2022	GW	123-21441	LOST CREEK 5	SI

General Comment:

This is a follow up to prior inspection document #69910154. 1 out of 2 CA were not corrected.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 267813 Type: WELL API Number: 123-21441 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: No FIRR was submitted.Corrective Action: When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b.Date: 10/13/2023**BradenHead**Date of Last Brhd Test: 12/01/2021Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No updated annual BH test on file. Submit reports. Form 17 #403257040 indicates it was last tested on 12/8/20.

09/22/2023

Corrective Action: Submit reports as per Rule 419.

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 10/9/23 at approximately 0917hrs I, Inspector Adam Burns, Conducted an on-site inspection to prior inspection document #699107154 at Lost Creek 5 of O'Brien Energy Resources Corp.</p> <p>API #05-123-21441 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>No updated annual BH test on file. Submit reports. Form 17 #403257040 indicates it was last tested on 12/8/20. Submit reports as per Rule 419. With a Corrective Action date of 9/22/23</p> <p>No FIRR was submitted. When a Field Inspection Report includes a corrective action, upon completion of that corrective action the Operator will submit to the Director a Field Inspection Report Resolution Form ("FIRR"). Per rule 210.b. With a Corrective Action date of 10/13/23</p> <p>1 out of 2 CA's were corrected</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/11/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403557337	INSPECTION SUBMITTED	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281158
699107547	Inspection Photo	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6281130