

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2023

Submitted Date:

10/17/2023

Document Number:

697504891

**FIELD INSPECTION FORM**Loc ID 421908 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cduran@rockiesresourcesllc.com	
		janderson@rockiesresourcesllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421912	WELL	SI	02/01/2021	OW	123-33110	Wagner 11-65 11-1H	RI

**General Comment:**

This is a Stormwater Inspection for a shared access road.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, there is a portion along the southern access road at ~2.4 miles from CR57 where a BMP has not been properly installed and is not sufficient to control stormwater erosion off the lease road. Both Upland and CCRP will have to coordinate on the corrective action.

Staff, Chris Binschus, contacted Operator representatives on 10/5/2023 communicating the observation and the need to coordinate with Upland.

Corrective Action: CCRP shall coordinate with Upland Exploration on the corrective action work to comply with Rule 1002.f.

The corrective action date is the date the issue was observed out of compliance.

Date: 10/04/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403563022	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6287024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6287024</a>
697504893	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6287010">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6287010</a>