

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2023

Submitted Date:

10/27/2023

Document Number:

710500061**FIELD INSPECTION FORM**Loc ID 324498 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Newville, Toni		toni_newville@oxy.com	<a href="#">OXY Sheep Mountain Inspections</a>
OXY, COGCC		COGCCInspections@Oxy.co	<a href="#">OXY Sheep Mountain Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211806	WELL	PR	02/01/2022	CO2	055-06041	DIKE MOUNTAIN UNIT 4-13	EI
324498	LOCATION	AC			-	DIKE MOUNTAIN UNIT-628S70W 13SENW	EI

**General Comment:**[This is an Environmental Inspection for the Dike Mountain Unit 4-13; Location # 324498, active well location located in Huerfano County, Co.](#)[This inspection will follow up a Reclamation inspection conducted on 10/11/2023, Document # 713600296](#)

**Location****Lease Road:**

Type	Access		
comment:	At the time of Inspection the access road was being reworked, BMP's were being added to stabilize roadway. Corrective action date of 10/11/2023 still applies. Repair entire roadway so that it is accessible in all weather conditions.		
Corrective Action:	Comply with Rule 603.I.	Date:	10/11/2023

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 211806 Type: WELL API Number: 055-06041 Status: PR Insp. Status: EIFacility ID: 324498 Type: LOCATION API Number: - Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
Grading activities as the only BMP is not sufficient to stabilize the road. BMP's along the steep road must be selected based off site-specific conditions and must be implemented in accordance with good engineering practice. Corrective action will remain out of compliance until completed.	sanchezcc	10/26/2023
Install or repair required BMPs per Rule 1002.f.(2)		

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500063	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300248">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300248</a>