

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2023

Submitted Date:

10/27/2023

Document Number:

710500061**FIELD INSPECTION FORM**Loc ID 324498 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
OXY, COGCC		COGCCInspections@Oxy.co	OXY Sheep Mountain Inspections
Newville, Toni		toni_newville@oxy.com	OXY Sheep Mountain Inspections
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211806	WELL	PR	02/01/2022	CO2	055-06041	DIKE MOUNTAIN UNIT 4-13	EI
324498	LOCATION	AC			-	DIKE MOUNTAIN UNIT-628S70W 13SENW	EI

General Comment:

This is an Environmental Inspection for the Dike Mountain Unit 4-13; Location # 324498, active well location located in Huerfano County, Co.

This inspection will follow up a Reclamation inspection conducted on 10/11/2023, Document # 713600296

Location**Lease Road:**

Type	Access		
comment:	At the time of Inspection the access road was being reworked, BMP's were being added to stabilize roadway. Corrective action date of 10/11/2023 still applies. Repair entire roadway so that it is accessible in all weather conditions.		
Corrective Action:	Comply with Rule 603.I.	Date:	10/11/2023

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211806	Type: WELL	API Number: 055-06041	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

Facility ID: 324498	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
---------------------	----------------	---------------	------------	------------------

COGCC Comments

Comment	User	Date
Grading activities as the only BMP is not sufficient to stabilize the road. BMP's along the steep road must be selected based off site-specific conditions and must be implemented in accordance with good engineering practice. Corrective action will remain out of compliance until completed.	sanchezcc	10/26/2023
Install or repair required BMPs per Rule 1002.f.(2)		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403574832	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300256
710500063	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6300248