

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2024

Submitted Date:

04/08/2024

Document Number:

697505246

**FIELD INSPECTION FORM**Loc ID 415742 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 27742

Name of Operator: EOG RESOURCES INC

Address: P O BOX 4362

City: HOUSTON State: TX Zip: 77210-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		kristen_limongelli@eogresources.com	
		tracy_opp@eogresources.com	
		penny.garrison@state.co.us	
		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416058	WELL	AL	05/26/2016	LO	123-31245	Garden Creek 3-05H	RI

**General Comment:**

This is a Final Reclamation inspection in response to ECMC Field Inspection Report (FIR) Doc.# 696306059 submitted on March 5, 2024.

Inspected Facilities										
Facility ID:	416058	Type:	WELL	API Number:	123-31245	Status:	AL	Insp. Status:	RI	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>Comment from previous FIR:  AL - Conductor and Well Celler appear to still be present at Wellsite. Form 4 Sundry #2452104 for Abandon Permit was filed on 05.27.2016 and Approved on 08.15.2016. Indicating that operation has not been conducted. Well has not been drilled. Location has not been constructed and site will not be used in the future. Inspection demonstrates that location construction and some part of wellbore was initiated without appropriate documentation.</div>								
Corrective Action:		<div>Corrective Action from previous FIR:  Operator is to provide full description of activity and current status at this location. Location and APD were indicated to have been abandoned without construction or drilling (Sundry #2452104). Provide these details on a Form 4 Sundry Notice. If any casing was placed, a Form 5 Drilling Completion Report is required. Final reclamation and pad closure need to be concluded.  Operator has failed to perform the corrective action; therefore, the corrective action remains applicable.</div>						Date:		04/02/2024
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IRRIGATED

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built **Fail** \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

<p>Operator submitted a Form 4 (Doc.# 2452104) on 5/27/2016 to abandon the permit and that the location has not been constructed.</p> <p>Based on Google Earth from 9/7/2013 and 2024 field inspections, the location was constructed and conductor set. Refer to the attached inspection photos.</p> <p>On 4/8/2024, ECMC Reclamation Specialist left a voicemail with the Principal Agent regarding the observed compliance issue.</p>		Date <b>04/30/2024</b>
Corrective Action:	<p>Comply with Rule 1004. Remove all surface equipment, remove gravel and recontour. All areas compacted by drilling and subsequent oil and gas operations shall be cross-ripped to a depth of eighteen (18) inches. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.</p>	
<p>Overall Final Reclamation <b>Fail</b>      Well Release on Active Location <input type="checkbox"/>      Multi-Well Location <input type="checkbox"/></p>		

ECMC Comments		
Comment	User	Date
To date, the Operator has not reached out to ECMC Staff and the corrective action from the previous inspection has not been resolved.	binschusc	04/08/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403746558	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6499989">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6499989</a>
697505247	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6499987">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6499987</a>