

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403766626

Date Received:
04/23/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tyranny Bergin</u>	<u>970-313-5547</u>	<u>EHSCOGCCInspections@pdce.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 701900930
Inspection Date: 06/02/2023 FIR Submit Date: 06/26/2023 FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC Company Number: 69175
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 322959

Location Name: BROWN-64N67W Number: 20SWNW County: _____
Qtrqr: SWN Sec: 20 Twp: 4N Range: 67W Meridian: 6
W
Latitude: 40.300440 Longitude: -104.919860

FACILITY - API Number: 05-123-00 Facility ID: 322959

Facility Name: BROWN-64N67W Number: 20SWNW
Qtrqr: SWN Sec: 20 Twp: 4N Range: 67W Meridian: 6
W
Latitude: 40.300440 Longitude: -104.919860

CORRECTIVE ACTIONS:

1 CA# 173849

Corrective Action: Comply with Rule 1002.f. Install or repair required BMPs per Rule 1002.f. BMP's shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to rule 1004.

Date: 06/02/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED Date of Completion: 04/19/2024

Operator Comment: Disced, seeded and straw crimped. The erosion issue on the southwest side of the site has been mitigated and filled in on our site and the farmer fixed his ditch on the edge of our site so that no water should be flowing through our pad moving forward. CA complete.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Disced, seeded and straw crimped. The erosion issue on the southwest side of the site has been mitigated and filled in on our site and the farmer fixed his ditch on the edge of our site so that no water should be flowing through our pad moving forward. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: H&S Specialist-Operations

Date: 4/23/2024 2:59:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403766643	Brown 1
403766651	Brown 2
403766658	Brown 3
403766662	Brown 4

Total Attach: 4 Files