



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200256

Date <u>10/29/11</u>	Well Owner <u>POC</u>	Well No. <u>11-32H</u>	Lease <u>Rothamel</u>
County <u>Weld</u>	State <u>Colorado</u>	<u>ZJBS1</u>	Field
Charge to <u>Petroleum Development Corporation</u>			Charge Code
Address <u>1775 Sheerman Street, Suite 3000 (ENSLG 82)</u>		<u>AFF</u>	For Office Use Only
City, State <u>Denver, Colorado 80203</u>		<u>Coding</u>	
Pump Truck No. <u>1208</u>	Code	Bulk Truck No. <u>1211/1217</u>	Code
Type of Job	Depth	By <u>[Signature]</u>	
<u>Surface</u> <u>9 5/8" CSG - 9 1/2" 13 1/2" Hbk</u>	Bottom of Surface	Fl. <u>885</u>	To
Plug	Plug Landed @ <u>829</u>	Fl. <u>874</u>	
Production	Pipe Landed @ <u>874</u>	Time On <u>1100</u>	
		<u>Plug Down 1545</u>	

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat	730	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele <u>4</u> #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
<u>9 5/8"</u>	<u>Centralizers</u>	<u>8</u>		<u>80°</u>	
"	<u>Cement Basket</u>	<u>1</u>			
"	<u>Guide Shoe</u>	<u>1</u>			
"	<u>AFL FLOAT INSERT</u>	<u>1</u>			
	<u>Box Threadlock</u>	<u>1</u>			
	<u>Mixing Rate - 4BPM</u>	<u>Slurry Vol 1.18</u>	<u>ET/SK</u>	<u>Water Temp 54°F</u>	
	<u>Displacement Rate - 4BPM</u>	<u>Slurry wt 15.2 PPG</u>			
	<u>Plug landed @ 500 PSI</u>	<u>Total Slurry Vol - 153.4 BBLs Cement</u>			
Remarks: <u>PRE-Flush w/ 30 BBLs H₂O</u>	Tax Reference Code		Sub Total		
<u>Displace w/ 64 BBLs H₂O</u>	State <u>CO 2.9 %</u>		Tax		
<u>Circulate 5 BBL Cement</u>	Disc.		Total		
Truck No	Code	State Mileage	Nebraska	Colorado	Wyoming
<u>1208</u>		Pump Truck		<u>34</u>	
<u>1211/1217</u>		Bulk Truck		<u>34/34</u>	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Justin Kenny & Demetrio

Received By [Signature]

Customer or His Agent