

FORM 5A

Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 400371281

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 10203
2. Name of Operator: BLACK RAVEN ENERGY INC
3. Address: 1331 17TH STREET - #350
City: DENVER State: CO Zip: 80202
4. Contact Name: Scott Ritger
Phone: (303) 887-9266
Fax: (303) 308-1590

5. API Number 05-087-05513-00
6. County: MORGAN
7. Well Name: GLENN-BIDDLE
Well Number: A-2
8. Location: QtrQtr: NWSW Section: 32 Township: 2N Range: 57W Meridian: 6
9. Field Name: ADENA Field Code: 700

Completed Interval

FORMATION: J SAND Status: TEMPORARILY ABANDONED Treatment Type:

Treatment Date: End Date: Date of First Production this formation:

Perforations Top: 5547 Bottom: 5555 No. Holes: 48 Hole size: 38/100

Provide a brief summary of the formation treatment: Open Hole: [ ]

Set a CIBP at 5558', above the existing perforations (5561-5566'). Perforated the top of the J sand from 5547 to 5555'. CIBP ticket is attached.

This formation is commingled with another formation: [ ] Yes [X] No

Total fluid used in treatment (bbl): Max pressure during treatment (psi):

Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment: Min frac gradient (psi/ft):

Total acid used in treatment (bbl): Number of staged intervals:

Recycled water used in treatment (bbl): Flowback volume recovered (bbl):

Fresh water used in treatment (bbl): Disposition method for flowback:

Total proppant used (lbs): Rule 805 green completion techniques were utilized: [ ]

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:

Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:

Test Method: Casing PSI: Tubing PSI: Choke Size:

Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:

Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production: Excessive water cut.

Date formation Abandoned: Squeeze: [ ] Yes [ ] No If yes, number of sacks cmt

\*\* Bridge Plug Depth: \*\* Sacks cement on top: \*\* Wireline and Cement Job Summary must be attached.

Comment:

After unsuccessful swab test of new perforations (high water cut) the well has been returned to TA status, with no production facilities set.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Scott Ritger

Title: Geologist Date: \_\_\_\_\_ Email sritger@tidenver.com

**Attachment Check List**

Att Doc Num	Name
400371326	WIRELINE JOB SUMMARY

Total Attach: 1 Files

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>

Total: 0 comment(s)