



WELL LOCATION CERTIFICATE

SECTION: 27
TOWNSHIP: 6N
RANGE: 67W

LAT: 40.46535°N
LONG: 104.90768°W

THIS MAP DOES NOT REPRESENT A BOUNDARY SURVEY

FOUND #6 REBAR WITH
3.25" ALUM. CAP LS 20685
LAT: 40.46516°N
LONG: 104.88911°W

FOUND #6 REBAR WITH 3.25" BRASS CAP

S 89°36'59" E 2584.39'

S 89°36'47" E 2584.30'

495'
460'

N 89°36'53" W 4251.26'

495'
460'

TARGET #2
N 89°36'53" W
440.70'

TARGET #1

N 55°13'10" W
1296.61'

1245'

KODAK 4
NW1/4

N 00°04'35" E 2663.79'

NW1/4

NE1/4

S.27, T.6N., R.67W.

S 89°57'48" E 2591.40'

S 89°57'48" E 2591.04'

-100.0' WITNESS CORNER-
FOUND #6 REBAR WITH
3.25" ALUM. CAP LS 22098

S.28, T.6N., R.67W.

FOUND 5/8" SQUARE STEEL BAR WITH 2.5" ALUM. CAP LS 31169

N 00°04'35" E 2663.51'

SW1/4

SE1/4

SW1/4

POSITION FROM RECORD SURVEYS LOCATION IN LAKE

FOUND #6 REBAR WITH 3.25" ALUM. CAP LS ILLEGIBLE

FOUND #6 REBAR WITH 2.5" ALUM. CAP LS 31169


LAT: 40.45073°N
LONG: 104.90784°W

S 89°41'07" W 2598.85'

S 89°43'22" W 2598.16'

LAT: 40.45071°N
LONG: 104.88917°W

PROPOSED SPACING UNIT



NOTE
According to Colorado law, you must commence any legal action based upon any defect in this W.L.C. within three years after you discover such defect. In no event, may any action based upon any defect in this survey be commenced more than ten years after the date of the certificate shown hereon. (13-80-105 C.R.S.)

LEGEND

- = ALIQUOT MONUMENT AS DESCRIBED
- = CALCULATED POSITION



SHEET 2 OF 2

Brian T. Brinkman—On behalf of Lat40°, Inc.
Colorado Licensed Professional Land Surveyor No. 38175
DATE: 3/5/2013
PROJECT#: 2012167