

2115 117th Avenue
Greeley, CO 80634

Tel: 970.304.5000
Fax: 970.304.5099
www.nobleenergyinc.com



Land Department

April 7, 2015

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Article # 70132250000035339113

Bringelson Ranch, LLC
Denis L. Bringelson
48904 County Road 127
New Raymer, Colorado 80742

Re: WELL NAME(S): **BRINGELSON 1-28**
Request for Approval to Re-Enter and Re-Plug
Township 9 North, Range 58 West, 6th P.M.
Section 28: NW/4SW/4
Weld County, CO

Dear Mr. Bringelson:

On June 20, 2013, the Colorado Oil and Gas Conservation Commission (COGCC) enacted a new policy requiring that all operators of horizontal wells completed in the Niobrara Shale formation (the "Formation") to review the completion records for any well that penetrated the Formation that is located within fifteen hundred feet (1,500') of the anticipated bore hole of any such horizontal well.


In accordance with this COGCC policy Noble has evaluated the above captioned well(s) and has determined that it is necessary to re-enter and re-plug the well(s) in order to be adequately isolated from horizontal wells.

As such, Noble requests that you, the surface owner of the lands described above, grant Noble permission to re-enter and re-plug the well.


Thank you for your cooperation in this matter. If you have any questions or concerns, please feel free to contact me at the numbers listed on the enclosed business card.

Sincerely,

NOBLE ENERGY, INC.

By: 
Reggy Gray

OWNER: DENIS L. BRINGELSON

By: 
Denis L. Bringelson, Manager