




02469025

## REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)



To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_2. BBLS Discharged: 50 bbls water, 5 bbls oil BBLS Lost: - 0 -3. Contained on location: Yes X No \_\_\_\_\_4. Date and time of event: 2/1/87 3:00 pm5. Date and time reported to BLM: Not required6. Location of event: EMERALD 67X, NE SW, Sec 30, T2N, R102W  
Rangely Weber Sand Unit, Rio Blanco County, Colorado

7. Specific nature and cause of event

Flowline leak at steel to fiberglass flange

8. Describe resultant damage:

N/A

9. Time required for control of event: ± 15 minutes

10. Action taken to control and contain:

Shut off valve, fluid was contained and sucked up and taken  
to FEE 10 pit.

11. Action taken to prevent recurrence:-

Repaired flange

12. Cause of death:

N/A

13. Other agencies notified:

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO -  
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

14. Other pertinent information:

Signature T L Hunt 2/8/87 Date \_\_\_\_\_  
T. L. HurstTitle Area Supervisor

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.