

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2018

Submitted Date:

09/27/2018

Document Number:

691401088**FIELD INSPECTION FORM**
 Loc ID 318399 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:                     
**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241226	WELL	SI	07/01/2006	OW	123-09014	1415 CORP UNIT F 1	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	No wellhead sign posted.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/27/2018

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241226 Type: WELL API Number: 123-09014 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well was last produced Mar. of 2005. According to records there has not been an MIT performed on this well. Also according to rule 707.b. this well is improperly reported on production record as SHUT IN, this well appears to be TEMPORARILY ABANDON.

Corrective Action: Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3). Please cc me on all communications with dnr\_cogccengineering@state.co.us

Date: 10/11/2018**BradenHead**

Comment: Not plumbed to surface

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401777413	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592025">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592025</a>
691401089	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592012">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592012</a>