

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401971611

Date Received:

03/13/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Labowskie, Steve

steve.labowskie@state.co.us

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687903889

Inspection Date: 03/11/2019

FIR Submit Date: 03/11/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 311971

Location Name: COGBURN GAS UNIT A-M34N8W Number: 24NENE County: LA PLATA

Qtrqtr: NENE Sec: 24 Twp: 34N Range: 8W Meridian: M

Latitude: 37.181062 Longitude: -107.663521

FACILITY - API Number: 05-067- -00 Facility ID: 288738

Facility Name: COGBURN A Number: 4

Qtrqtr: NENE Sec: 24 Twp: 34N Range: 8W Meridian: M

Latitude: 37.181062 Longitude: -107.663521

CORRECTIVE ACTIONS:

1 CA# 123111

Corrective Action: Please comply with Rule 605.d.

Date: 03/13/2019

Response: CA COMPLETED

Date of Completion: 03/11/2019

Operator
Comment:

The evening of March 11, 2019 a lead operations technician was dispatched to location to check the coffin box leak reported in the inspection. Upon arrival he check the packing and performed maintenance on the packing and the coffin box. The maintenance included tightening everything upon the equipment. He observed for an

hour and no leaking was observed. The same technician returned to location the following day to ensure that the maintenance had resolved the issue and found the equipment to be functioning correctly and no leak occurring. BPX has addressed this issue.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: The evening of March 11, 2019 a lead operations technician was dispatched to location to check the coffin box leak reported in the inspection. Upon arrival he check the packing and performed maintenance on the packing and the coffin box. The maintenance included tightening everything upon the equipment. He observed for an hour and no leaking was observed. The same technician returned to location the following day to ensure that the maintenance had resolved the issue and found the equipment to be functioning correctly and no leak occurring. BPX has addressed this issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 3/13/2019 4:34:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files