

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

685100894**FIELD INSPECTION FORM**Loc ID 320321 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 240 W JESSUP STCity: BRIGHTON State: CO Zip: 80601**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arnold, Diana	303-659-8203	darnold@agcsi.com	
Gomez, Jason		jason.gomez@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Mattox, Jennifer	303-692-3144	jennifer.mattox@state.co.us	environmental protection specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203445	WELL	SI	07/01/2018	OW	001-09004	COMANCHE CREEK 2-14	SI

General Comment:

Location				
Lease Road:				
Type				
comment:				
Corrective ActionL				Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	weeds inside pump jack fence, motor house, and by wellhead see pic 1, 2, 5			
Corrective Action:	Comply with Rule 603.f .			Date: 05/12/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	4' barb wire fence			
Corrective Action:				Date:
Equipment:				
Type: Pump Jack		#		corrective date
Comment:				
Corrective Action:		Date:		
Type: Prime Mover		#		
Comment:		What appears to be leaking fluid from counter weight on pump jack stained soil. see pic 3, 4, 6. Unmarked barrel with no containment appears to be leaking stained soil see pic 7		
Corrective Action:		Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. Date: 05/04/2019		
Type: Deadman # & Marked		# 4		
Comment:				
Corrective Action:		Date:		
Type:		#		
Comment:				
Corrective Action:		Date:		
Venting:				

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	203445	Type:	WELL	API Number:	001-09004	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Well appears to be shut in."/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 5/2/19 at approximately 1100, Inspector Justin Medina conducted an on-site inspection at 001-09004 Comanche Creek 2-14 Schreider & Company INC at Weld County Colorado. While there, I observed shut in well.</p> <p>The following possible compliance issues were observed while on location: weeds inside pump jack fence, motor house, and by wellhead see pic 1, 2 , 5 Comply with Rule 603.f . 5/12/19 What appears to be leaking fluid from counter weight on pump jack. see pic 3, 4 , 6. Unmarked barrel with no containment appears to be leaking see pic 7 Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 5/4/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	05/02/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100895	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814141