

Texas Mountain Federal 20-1
API: 05-103-07288
Inspection: 679704134



Photo 1. Location looking southeast.

API: 05-103-
Inspection: 67970



Photo 2. Gas leak in upper part of well head.