

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2019

Submitted Date:

06/06/2019

Document Number:

679704383

FIELD INSPECTION FORM

Loc ID 420981 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421489	WELL	PR	08/19/2011	OW	103-11855	EMERALD 94X	PR
421610	WELL	PR	02/01/2018	OW	103-11858	EMERALD 93X	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 6-6-2019 at approximately 16:15, inspector Rick Moran, conducted a routine well inspection at Chevron's well Emerald 93X & 94X in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Well head sign missing emergency contact number & 911. Photos 2 & 3. Complete by 7-8-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704383.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Both well head signs are missing the operator emergency phone number "911". The emergency phone is present on the entrance to the lease road.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	07/08/2019

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Deadman # & Marked	#		corrective date
	# 4		
Comment:			
Corrective Action:		Date:	
Type: Submersible Pump	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 421489 Type: WELL API Number: 103-11855 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

Facility ID: 421610 Type: WELL API Number: 103-11858 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402067399	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842872
679704384	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4842867